



V = VAPORE
STEAM
VAPEUR

A = ARIA C.
AIR.C
AIR.C

PRESOSTATO MATER CON BOX MATER - PRESSURE SWITCH IN BOX PRESSOSTAT - MATER AVEC BOX	1-4" M	0 - 6 Bar	V	Cod. 120.01
	1-4" M	0 - 9 Bar	V	Cod. 120.09



PRESOSTATO MATER SENZA BOX
MATER - PRESSURE SWITCH WITHOUT BOX
PRESSOSTAT - MATER SANS BOX

1-4" M	0 - 6 Bar	V	Cod. 120.10
---------------	-----------	----------	-------------



PRESOSTATO MANUALE DI SICUREZZA SOVRAPRESSIONE
MANUAL PRESSURE- SWITCH FOR SAFETY OVERLOAD
PRESSOSTAT MANUEL POUR SECURITE SUR-PRESSION

1-4" M	3 - 7,5 Bar	V	Cod. 120.07
---------------	-------------	----------	-------------



PRESOSTATO CEME
CEME - PRESSURE SWITCH
PRESSOSTAT - CEME

1-4" M	0 - 6 Bar	V	Cod. 120.03
---------------	-----------	----------	-------------



PRESOSTATO
PRESSURE SWITCH
PRESSOSTAT

1-4" F	0 - 11 Bar	A	Cod. 120.02
---------------	------------	----------	-------------